REVISED 5-7-87 THIND СаБТе FMEA NO. W 4.27.2 2293287-503 SHUTTLE COTY DHG NO. CRITICAL LIEMS LIST ESSUED 10-14-8<u>6</u> CRITICALITY 2/1R SHEET FATLURE MODE AND FATLURE EFFECT CAUSE ON END ITEM RATIONALE FOR ACCEPTANCE Loss of Limit DN SW Tilt will not move in DESIGN FEATURES down direction (CH). Shurt to GMD The W4 PTU cable is a 44-inch long, 25-wire assembly terminated by 37 pin connectors at Worst Case: each end. The video and sync/cmd wires are shielded Twinax shielded and twisted pairs of #24 wire. The cable connects the TVC and PTU. Connector types KJG6E14H35SM16 have Tilt will not move in been seletted. down direction (CW) for elbow camera to permit arm The cable design is taken from the successfully flown Apollo program. The design is a s Lowage . cable-connector assembly in which the wire terminations are protected from excessive flexture at the joint between the wire and the connector terminal. The load concentration is moved away from the conductor connection and distributed axially along the length of the conductors encapsulated in a potted-taper profile. This technique also protects the assembly from dirt and entrapped moisture which could cause problems in space. The cable and its components meet the applicable requirements of NASA, Hilltary and REA specifications. These requirements include: General/Mechanical/Electrical Features Design and Construction Naterials Terminal Solderability Environmental Qualification Marking and Serialization
 Traceability and Documentation

REVISED 5-7-87 СаБ е TINIT DWG NO. 2293287-503 SHUTTLE CCTV N 4.27.2 FMEA NÚ. LSSUED 10-14-86 CRITICAL ITEMS LIST SHEET 2 CRITICALITY 2/1R FATIURE EFFECT FAILURE HODE AND NATIONALE FOR ACCEPTANCE ON FAID LIEM CAUSE OUALIFICATION TEST Tilt will not move in Loss of Limit DN SH down direction (CM). Qualified by [.] similarity to previous successful space programs and 2.) by use during Short to GMD qualification tests of CCTV LRUs. Worst Case: ACCEPTANCE TEST Tilt will not move in down direction (CV) for The cable acceptance test consists of an ohmmeter check to assure that each wire elbow camera to permit arm connection is present and intact. Results are recorded on data sheets. stowage. OPERATIONAL TEST The following tests verify that CCTV components are operable and that the commands from $\dot{\cdot}$ the PHS (AZAT) page) switch, through the RCU, through the sync lines to the Camera/PTU, to the Camera/PTU command decoder are proper. The tests also verify the camera's ability to produce video, the YSD's ability to route video and the monitor's ability to display video. A similar test verifies the MDM command path. Pre-Launch on Orbiter Test/In-Flight Test Power CCTV System. Select a monitor via the PHS panel, as destination and the camera under test as Send "Camera Power On" command from PHS panel. Select "External Sync" on monitor. Observe video displayed no monitor. If video on monitor is synchronized (i.e., stable raster), then this indicates that the camera is receiving composite sync from the RCD and that the camera is producing synchronized video. Send Pan, Tilt, Focus, Zoom, ALC, and Gamma commands and visually (either via the monitor or direct observation) verify proper operation. 7. Select Downlink as destination and camera under test as source. Observe video routed to downlink. 9. Send "Camera Power Off" command via PHS panel. 10. Repeat Steps 3 through 9 except issue commands via the MDN command path. This urness that the CCTV equipment is operational if video is satisfactory.

REVISED 5-7-87 ÜNT Cable FMEA NO. W 4.27.2 SHUTTLE CETY 2293287-503 DUG NO. CRITICAL LIEMS LIST ISSUED 10-14-86 CRITICALLITY 2/1A SHEET FAILURE MODE AND FATEURF EFFECT CAUSE ON END ITEM RATIONALE FOR ACCEPTANCE Loss of Limit DN SW Tilt will not move in QA/INSPECTION down direction (CW). Short to GND Procurement Control - Wire, commectors, solder, etc. are procured from approved vendors and suppliers which meet the requirements set forth in the CCTV contract and Quality Worst Case: Plan Work Statement (MS-2593176). filt will not mave in Incoming Inspection & Storage - Incoming Quality inspections are made on all received down direction (EW) for materials and parts. Results are recorded by lot and retained in file by drawing and elhow camera to permit arm: control numbers for future reference and traceability. Accepted items are delivered to stowage. Material Controlled Stures and retained under specified conditions until cable fabrication is required. Mon-conforming materials are held for Haterial Review Board (MRO) disposition. $\{PA1-307, PAI, IQC-53\}$. Assembly & Test - Prior to the start of assembly, all items are verified to be correct by stock room personnel as the Items are accumulated to form a kit. The items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL). Specific instructions are given in assembly drawing notes and applicable documents called out in the Fabrication Procedure and Record (FPR-2291287). These are 2280800 -Process Standard crimping flight connector contacts, 2200801 - Process Standard in-line solicing of standard interconnecting wire using Raychem solder sleeves, 2280876 -Process Standard marking of parts or assemblies with epoxy colors, 2280876. Potting naterial and test procedure (TP-AT-2293287). Quality and DCAS Inspections are performed at the completion of key operations. Preparation for Shipment - When fabrication and test is complete, the cable assembly is packaged according to 2280746, Process Standard for Packaging and Handling Guidelines. All related documentation including assembly drawings, Parts List, ABPL, Test Data, etc. is gathered and held in a documentation folder assigned specifically to each cable assembly. This folder is retained for reference.

D2000

FMEA NO. <u>U 4.27.2</u> CRITICALITY <u>2/1R</u>	·	SINTTLE CCTV CRITICAL ITEMS LIST	DWIT Cable OM6 NO. 2293287-503 ISSUED TO-14-86 SHEET 4 OF 5
FAILURE MODE AND CAUSE	FATLURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
Loss of Limit DN SW Short ta GND	Tilt will not move in down direction (CM). Morst Case: Tilt will not move in down direction (CW) for elbow camera to permit arm stowage.	FAILURE HESTORY There have been no reported failures during RCA to	esting, pre-flight or flight.

REVISED 5-7-87

REVISEO 5-7-87 UNIT Cable FMEA NO. W 4.27.2 SHUTTLE CCTY DWG NO. 2293287-503 CRITICAL ITEMS LIST ISSUED 10-14-86 CRITICALITY 2/18 SHEET FATLURE MODE AND FAILURE EFFECT CAUSE ON END ITEM RATIONALE FOR ACCEPTANCE Loss of Limit ON SM Tilt will not move in **IIPERATIONAL EFFECTS** down direction (CW). Shurt to GMD Loss of ability to position the Fibou camera. Possible inability to stow the AMS if the Worst Case: elbow camera physically interferes with a payload. If RMS cannot be stowed the port Tilt will not move in payload bay door cannot be closed. Loss of crew and vehicle. down direction (CW) for elbow camera to permit arm stuwage. CREW ACTIONS Perform EVA to reposition the elbow camera, use RMS motion to reposition the camera, or jettison the RMS. CREW TRAINING Crew should be trained in contingency EVA and AMS operations procedures. **HISSION CONSTRAINT** Do not manifest Elbow camera for any flight where the payload and the elbow camera can interfere with each other (for any pan or tilt angle). If the camera must be flown do not change the camera position until the interfering payload is deployed.